



RocketPlan Gallery - Dataset Summary

Generated summary for a structured restoration photo dataset. The summary matches CSV exports with RocketReport context, notes, room sections, equipment records, and generated report outputs.

Dataset overview

Metric	Value	Source
Photos	637	photos.csv
Rooms / stages	4	rooms.csv + RocketReport room headings
Notes	29	notes.csv
Completed report records	5	reports.csv
Equipment-room records	1	equipment_room.csv + RocketReport equipment table
Date range	Jan 5, 2026 – Jan 15, 2026	photos.csv timestamps

Project / property / claim context

Field	Matched value
Project alias	ILM-2026-0002 Lynn Owen
Our File #	RP-26-2049
Project manager	Hutch Hillebert
Location of loss	203 Finch Street, Clinton, NC, 28328, US
Property classification	Single Unit
Claim number	060701958
Adjuster	Damian Vizcarron

Room and photo context

Room / report section	Photos	Date range	Report pages	Matched context
Assessment	30	2026-01-05	7–21	Initial assessment, Adjuster coordination, Photo documentation
Kitchen	178	2026-01-08 - 2026-01-15	22–110	AFD placement, Cabinet cleaning, Wall / trim / surface cleaning, Appliance exterior cleaning, Photo documentation
Content Cleaning	408	2026-01-12 - 2026-01-13	111–256, 265–322	Content manipulation, Content cleaning, Boxing contents, Returning contents, Consumables usage, Photo documentation
Over View	21	2026-01-15	257, 323–333	Equipment tracking, Sketch / overview documentation, Photo documentation

Scope / work-context tags

Initial assessment	Adjuster coordination	AFD placement
Content manipulation	Content cleaning	Cabinet cleaning
Wall / trim / surface cleaning	Appliance exterior cleaning	Boxing contents
Returning contents	Equipment tracking	Photo documentation
Sketch / overview documentation	Consumables usage	Invoice / payment activity

Scope / work summary matched to photos

- Placing an AFD.
- Manipulate all contents, including furniture, pictures, decorations, knickknacks, and related items.
- Wipe and clean contents with chem sponges, 9D9, and Vital Oxide.
- Wipe clean walls, trim, cabinets, surfaces, and related affected areas.
- Box contents after cleaning and put contents back after surfaces were cleaned.
- Clean exterior of appliances including double oven, fridge, microwave, dishwasher, and stove top.
- Remove AFD.
- Complete photo documentation, adjuster communication, sketch/overview documentation, and administrative work.
- Travel time noted as 1.5 hours one-way / 3 hours total per day.

Consumables listed: Chem sponges, Terry towels, Microfiber cloths, 9D9, Vital Oxide, Disposable gloves, Respirator

Work activity timeline

Date	Activity context	Matched room/stage	Source
Jan 5, 2026	Initial contact, loss intake, adjuster contact, assessment planning, and assessment photo capture.	Assessment	RocketReport project summary, photos.csv, notes.csv
Jan 8, 2026	Adjuster walk/scope discussion, AFD placement, cabinet cleaning started, and deposit collection activity.	Kitchen, Over View	RocketReport project summary, notes.csv, equipment_room.csv, photos.csv
Jan 9, 2026	Deposit recorded and affected kitchen-area cleaning continued.	Kitchen	RocketReport project summary, notes.csv, photos.csv
Jan 12, 2026	Contents manipulated, packed, cleaned, boxed, and tracked with room notes and photo documentation.	Content Cleaning	RocketReport project summary, notes.csv, photos.csv
Jan 13, 2026	Content cleaning continued; shelves, walls, and remaining cleaning activity documented.	Content Cleaning	RocketReport project summary, notes.csv, photos.csv
Jan 15, 2026	Cabinet cleaning finalized, AFD removed / equipment period ended, overview photos and equipment summary captured.	Kitchen, Over View	RocketReport project summary, equipment_room.csv, photos.csv
Jan 16-22, 2026	Report outputs, invoice/approval notes, payment collection notes, and adjuster follow-up activity recorded.	Project	reports.csv, notes.csv
Feb 6-16, 2026	Post-report estimate/revision follow-up and adjuster finalization notes recorded.	Project	notes.csv

Notes coverage

Note tag / activity label	Count
Adjuster	14
General note	8
Cleaning	6
Scope	4
Payment	4
AFD	4
Contents / boxes	1
Consumables	1

Generated reports and report settings

Report	Status	Created	Paired metadata
ILM-2026-0002 Lynn Owen - RocketReport	Completed	Jan 16, 2026, 12:07 PM	photos=all; photo notes=all; notes=bookmark; scope of work=yes; equipment list=yes; moisture logs=yes; date range=all; format=expanded
Owen, Lynn - Photos	Completed	Jan 16, 2026, 7:02 PM	photos=all; photo notes=none; notes=none; scope of work=no; equipment list=no; moisture logs=no; date range=all; format=compact
Owen, Lynn - Dry Logs	Completed	Jan 16, 2026, 7:05 PM	photos=none; photo notes=none; notes=none; scope of work=no; equipment list=no; moisture logs=yes; date range=all; format=compact
Owen, Lynn - Photo	Completed	Jan 16, 2026, 7:06 PM	photos=all; photo notes=none; notes=none; scope of work=no; equipment list=no; moisture logs=no; date range=all; format=compact
Owen Photo report	Completed	Jan 22, 2026, 5:24 PM	photos=all; photo notes=all; notes=all; scope of work=yes; equipment list=yes; moisture logs=yes; date range=all; format=compact

Source CSV coverage

File	Rows	Columns	Use in gallery
project.csv	1	15	Project-level identifiers and timestamps
properties.csv	1	23	Property classification and property-link context
locations.csv	1	15	Unit/location name and property relationship
rooms.csv	4	14	Room IDs, room type IDs, location relationship
photos.csv	637	21	Photo identity, storage paths, timestamps, room relationships
notes.csv	29	16	Project and room notes / work activity timeline
equipment_room.csv	1	13	Equipment deployed by room with date-in/date-out
reports.csv	6	10	Generated reports, report status, settings, and PDF URLs

Privacy note

The gallery display redacts phone numbers and email addresses where the redacted fields are used. External sharing should use a reviewed package with confirmed data rights and any required redaction policy.